Lockhood Aircraft Co Pro. Box 105 Sun Valley, Californ		Engineering S Change Propose		<u>x</u> X1	0	
					<u> </u>	
No. LAC - 2 Rev. #1	Date 3-5	<b>c</b> o	Affected Activ OPP (1)		X) Pr	roject
Name of Major Compos			Subannembly			& Model
Airplane	Fue	1 System	•			
Title of Proposals	Fuel System V	ent				
Nature of Proposals						
The fuel vent systemathis modification conservice bulletins in	an be seen in	ified per the attac	S.B. 369 & S.B hed preliminar	. 372. y runs (	Detai	ils of two
77.					٠ بر انداز ا	AN (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
	•		A STATE OF STATE			
The state of the s	or the second	$\varphi = \varphi$				Buck Barrel
Reason for Proposali					144	
load factors could prescribed in S.B. 36	ich causes fue these high pre possibly lead 59 & S.B. 372	el to be pressures sin to struct	imped into the multaneously coursel damage.	sump to ombined The vent	with syst	iru the high
u psi and higher white vent lines. Also,	ich causes fue these high pre possibly lead 59 & S.B. 372	el to be pressures sin to struct	imped into the multaneously coursel damage.	sump ta ombined The vent es to 2	with syst psi w	iru the high tem then usi
u psi and higher white vent lines. Also, to load factors could produce the could pro	ich causes fue these high pro- possibly lead 59 & S.B. 372 552 hA fuels.	el to be pressures sin to struct	imped into the multaneously coursel damage.	sump ta ombined The vent es to 2	with syst psi w	iru the high tem then usi
li psi and higher white vent lines. Also, to load factors could produce the could produce the could be considered in S.B. 30 LFIA or MIL Spec. 29 Setimated Cost and Tanding Redditional Funding Redditional Funding Red.	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.	el to be pressures sin to struct	imped into the multaneously coursel damage.	sump ta ombined The vent es to 2	with syst psi w	high high hen usi
li psi and higher white vent lines. Also, to load factors could produce the could pr	ich causes fue these high pre- possibly lead 59 & S.B. 372 552 hA fuels.	el to be pressures sin to struct	imped into the multaneously coursel damage.	sump ta ombined The vent es to 2	with syst psi w	high high hen usi
li psi and higher white vent lines. Also, to load factors could produce the could be a secribed in S.B. 30 LFIA or MIL Spec. 29 LFIA or MIL Spec. 29 Letimated Cost and Table timated Cost for R Letimated Cost for R Leditional Funding B.	ich causes fue these high pre- possibly lead 59 & S.B. 372 552 hA fuels. Time Involved equired None its or Parts equired None	el to be pressures sinto structo will keep	imped into the multaneously coursel damage. 'these pressure	sump ts ombined The vent es to 2	with syst psi w	high tem then usi
Li psi and higher white vent lines. Also, to load factors could produce the control of the contr	ich causes fue these high pre- possibly lead 59 & S.B. 372 552 hA fuels. Time Involved equired None its or Parts equired None	el to be pressures sin to struct	imped into the nultaneously coursel damage. these pressure	sump ta ombined The vent es to 2	with syst psi w	high tem then usi
Lipsi and higher white vent lines. Also, to load factors could produce the control of the contro	ich causes fue these high pre- possibly lead 59 & S.B. 372 552 hA fuels. Size or Parts equired None oposals	el to be pressures sinto structivill keep	umped into the multaneously coursel damage. These pressure these pressure Reflectively to the course of the course	sump ts ombined The vent es to 2  (Con	with syst psi w	high tem then usi attach STA
Lipsi and higher white vent lines. Also, to load factors could produce the could be described in S.B. 30 LFLA or MIL Spec. 29 LFLA or M	ich causes fue these high pre- possibly lead 59 & S.B. 372 552 hA fuels. The Involved equired None its or Parts equired None	el to be pressures sinto structivill keep	umped into the sultaneously coursel damage. these pressure these pressure Refectives	sump ts ombined The vent es to 2  (Con	with syst psi w	high tem then usi attach STA
upsi and higher white vent lines. Also, to load factors could proceed in S.B. 36 LFIA or MIL Spec. 29 LFIA or MIL Spec. 29 Legislated Cost and Tanding Buttienel Funding Buttienel Funding Buttienel Funding Buttienel Funding Butters Affected by Procedure  [V] Operating Procedure	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.  ine Involved equired None ite or Parts equired None oposals  Inter- changesbili	el to be pressures sinto structivill keep	umped into the sultaneously coursel damage. these pressure these pressure Refective Region Refective Research R	sump ts ombined The vent es to 2  (Con	with syst psi w	high high hen usi  STA  Perfor
li psi and higher white vent lines. Also, it load factors could proceed in S.B. 30 LFLA or MIL Spec. 29 LFLA or MI	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.  The Involved equired None its or Parts equired None oposals  Inter- changesbili	el to be pressures sinto structivill keep	mped into the sultaneously coursel damage. these pressure these pressure Refectively or Weight & Bal.	sump ts ombined The vent es to 2  (Con	with syst psi w	iru the high tem hen usi attach STA
li psi and higher white vent lines. Also, it load factors could pleaseribed in S.B. 36 LFLA or MIL Spec. 29  Satimated Gost and Tailed timated Cost for Ridditional Funding Procedure    Maintenance   Procedure   Maintenance   Procedure   Procedure	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.  The Involved equired None its or Parts equired None oposals  Inter- changesbili	El to be pressures sinto structivill keep  T Pilot  Handb	mped into the multaneously contains damage. These pressure these pressure Refectively or Weight & Bal.	sump ts ombined The vent es to 2  (Con	with syst psi w	iru the high tem then usi attach STA
upsi and higher white vent lines. Also, to load factors could proceed in S.B. 36 LFIA or MIL Spec. 29 LFIA or MIL Spec. 29 Legislated Cost and Tanding Buttienel Funding Buttienel Funding Buttienel Funding Buttienel Funding Butters Affected by Procedure  [V] Operating Procedure	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.  ine Involved equired None its or Parts equired None oposals  Inter- changesbili  Service Life  to Accomplish	El to be pressures sinto structivill keep  The Pilot Handbar Change in	mped into the multaneously contains damage. These pressure these pressure Refectively or Weight & Bal.	sump ts ombined The vent es to 2  (Con	with syst psi w	iru the high tem hen usi attach STA
li psi and higher white vent lines. Also, it load factors could pleaseribed in S.B. 36 LFIA or MIL Spec. 29  Setimated Cost and Tending Builditional Funding	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.  ine Involved equired None its or Parts equired None oposals  Inter- changesbili  Service Life  to Accomplish	El to be pressures sinto structivill keep  The Pilot Handbar Change in	mped into the multaneously contains the pressure these pressure these pressure from the pressure weight or weight & Bal.  Tield	sump ts ombined The vent es to 2  (Con  Tenese  Di No	with syst psi w	iru the high tem hen usi attach STA
li psi and higher white vent lines. Also, it load factors could produce the second of	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.  ine Involved equired None its or Parts equired None oposals  Inter- changesbili  Service Life  to Accomplish	El to be pressures sinto structivill keep  Piloto Handboa Change in	mped into the multaneously coursel damage. It is these pressure these pressure Refectively or Weight or Weight & Bal.  Field Evaluability  March 23, 19	sump ts ombined The vent es to 2  (Con  Tenese  Di No	with syst psi w	iru the high tem then usi attach STA
li psi and higher white vent lines. Also, it load factors could pleaseribed in S.B. 30 described in S.B. 30 LFIA or MIL Spec. 29 described in S.B. 30 LFIA or MIL Spec. 29 deditional Funding Blatimated Cost for Edditional Funding Blatimated Cost for Edditional Funding Blatimated by Procedure  [Y] Operating Procedure  [Y] Maintenance Procedure  [St. Man/Hrs. Req'd. Described Parts For 1 LAC pares Affected	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.  ine Involved equired None its or Parts equired None oposals  Inter- changesbili  Service Life  to Accomplish	El to be pressures sinto structivill keep  Piloto Handboa Change in	mped into the nultaneously contains damage. These pressure these pressure affective in the second se	sump ts ombined The vent es to 2  (Con  Tenese  Di No	with syst psi w	high tem then usi attach STA Ferfor
li psi and higher white vent lines. Also, to load factors could produce the second of	ich causes fue these high pre possibly lead 59 & S.B. 372 552 hA fuels.  ine Involved equired None its or Parts equired None oposals  Inter- changesbili  Service Life  to Accomplish	El to be pressures sinto structivill keep  Filoto Handbor Change in	mped into the multaneously coursel damage. It is made these pressure the pressure that the pressure the pressure that the p	sump ts ombined The vent es to 2  (Con  Tenese  Di No	with syst psi w	iru the high tem high tem hen usi stach STA